

PASSWORDS C220. C280, C360

- Press UTILITY / COUNTER
- Press ADMINISTRATOR SETTING
- Code is 12345678
- Press # 4 USER AUTHENTICATION / ACC TRACK
- Press # 1 GENERAL SETTINGS
- ACCOUNT TRACK – ON
- ACCOUNT TRACK INPUT METHOD – PASSWORD ONLY
- Press OK
- Press YES
- Press OK
- Press # 3 ACCOUNT TRACK SETTING
- Press # 1 ACCOUNT TRACK REGISTRATION
- Touch appropriate box number (001)

- EDIT
- Touch PASSWORD
- TYPE PASSWORD
- TYPE PASSWORD again to confirm
- Press OK
- Touch NAME
- TYPE NAME
- Press OK

(If you want to put limits and output permissions on users)

- Press OK
- Press CLOSE x 5



KONICA MINOLTA

TO LOG-IN

- Press INPUT
- TYPE PASSWORD
- Press OK
- Press the hard panel ACCESS KEY

TO LOG – OUT

- Press Hard panel ACCESS KEY
- Press YES